



Hyundai i20

Hatchback, 5 doors
From June 2026










	Airbag		Stored gas inflator		Seat belt pretensioner		SRS control unit		
	Battery low-voltage		Gas strut / Preloaded spring		High strength zone		Fuel tank		

ID No.	Version No.	Version date:	Page
			1 of 4

본문서는 현대자동차.기아의 정보자산으로 귀사와의 비밀유지계약 및 제반법률에 따라 법적 보호를 받습니다.


1. Identification / recognition

LACK OF ENGINE NOISE DOES NOT MEAN VEHICLE IS OFF: SILENT MOVEMENT OR INSTANT RESTART CAPABILITY EXISTS UNTIL VEHICLE IS FULLY SHUT DOWN.



2. Immobilisation / stabilisation / lifting

Immobilization:







1. Chock the wheels and pull the parking lever or EPB switch to set the parking brake.
2. For manual vehicles, place the gear lever in neutral (N). For automatic vehicles, shift the gear lever to the park (P) position.

For stabilize vehicle, crib at four points directly under the front and rear pillars using wooden blocks or equivalent objects

Lifting points under the vehicle:






3. Disable direct hazards / safety regulations

Low Voltage 12V Battery:

Access:


Pull the release lever to unlatch the hood. The hood should pop open slightly.


Raise the hood slightly, push the secondary latch up (1) inside of the hood center and lift the hood (2)


12 V

Disabling:

Turn the ignition switch off → Access to battery shown above → Disconnect the negative(-) terminal → Disconnect the positve(+) terminal


본문서는 현대자동차.기아의 정보자산으로 귀사와의 비밀유지계약 및 제반법률에 따라 법적 보호를 받습니다.

4. Access to the occupants

Steering column adjustment:



Seat adjustment:




MANUAL



2nd row seatback folding strap

Glass:

① : Laminated
②③ : Tempered
④ : Tempered




Tailgate:



Vehicle body ➔ Hardened Steel(100K↑)

Side





Bottom

5. Stored energy / liquids / gases / solids

		45/50l
		12V


R134a 410g

6. In case of fire

BATTERY RE-IGNITION! IR

Gas strut!

Risk of missile effect of tailgate.




본 문서는 현대자동차.기아의 정보자산으로 귀사와의 비밀유지계약 및 제반법률에 따라 법적 보호를 받습니다.

7. In case of submersion

Tilt the vehicle to one side to allow water to drain out of the vehicle.


8. Towing / transportation / storage

OK



Notice: The use of wheel dollies (1) or flatbed is recommended. Use a wheel lift or flatbed equipment.

Not OK



Notice : Do not tow with sling-type equipment (1). Do not tow the vehicle with the front wheels on the ground as this may cause damage to the vehicle (2).

10. Explanation of pictograms used

	Gasoline vehicle		Fuel tank content gasoline/ethanol		Bonnet
	Lifting points		Air-conditioning component		Battery low voltage
	Corrosives		Hazardous to the human health		Flammable
	Explosive		Acute toxicity		Environmental hazard

본 문서는 현대자동차.기아의 정보자산으로 귀사와의 비밀유지계약 및 제반법률에 따라 법적 보호를 받습니다.